

CLASSIFIED MESSAGE

DATE 2013Z 27 OCT 63

Approved For Release 2002/08/21 : CIA-RDP89B00569R000700150030-9

SECRET

ROUTING

1	4
2	5
3	6

TO : DIRECTOR

FROM : [REDACTED]

ACTION: OPS 1-7

INFO :

TOR 0134Z 28 OCT 63

PRIORITY

IN 97612

25X1A TO PRIORITY [REDACTED]

INFO [REDACTED]

CITE [REDACTED]

0101 25X1A

25X1A [REDACTED]

A. G-3235

25X1A

B. B-11052 [REDACTED]

C. HTA-2/D-19/4/75

D. 2.24/2.15

E. 9R/0-19-6000/8402/217-15-13-2-3/9L/0-19-6000/8402/219-19-10-2-3

F. (1) GOOD

(2) GOOD

(3) MEDIUM

(4) GOOD

(5) GOOD

(6) GOOD

(7) GOOD

G. 9R SMALL HAIRLINE MARK APPROXIMATELY ONE-HALF INCH LONG LOCATED AT EDGE OF DATA CHAMBER. APPEARS TO BE CAUSED BY SMALL PIECE OF LINT IN DATA CHAMBER. FRAME 0050 TRANSVERSE DRYING MARKS. SCATTERED PINHOLES FIRST FEW FRAMES. FRAMES 0077, 1244, 2422, DARKROOM SPLICE. FRAME 1331

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

Approved For Release 2002/08/21 : CIA-RDP89B00569R000700150030-9 Copy No.

25X1A

0101(IN 97612)

S E C R E T

PAGE TWO

TORN ON TACKY ROLLER CLEANER. FRAME 2395 EDGE TEAR. SMALL HAIRLINE INTERMITTENT BLACK EMULSION ABRASIONS DOWN CENTER OF FRAME AND 13/16 INCH FROM TITLED EDGE, FROM FRAME 2130 TO END OF FILM PLUS SEVERAL OTHER INTERMITTENT ABRASIONS OF SAME TYPE MOSTLY IN AND ALONG TITLED EDGE. APPARENTLY CAUSED BY CAMERA MAGAZINE SINCE BACK-UP TRAILOR FROM PROCESSORS SHOW NO INDICATIONS OF MACHINE ABRASIONS. 9L FRAMES 0134, 1249, 2411 DARKROOM SPLICES. FOLDOVER ON PRE-FLIGHT FRAMES. FRAME 1863-1866 WRINKLED IN DRYER.

H. EVERY EFFORT WILL BE MADE TO MOVE O.N. ON/ABOUT 30 OCT BY MIL AIR.
END OF MESSAGE

S E C R E T